

**SS MotorTrendz**

109 E Kiber St

Angleton, TX 77515

(979) 308-4588

Fax (979)-269-7347

Email: jerry@ssmotortrendz.com

Website: ssmotortrendz.com

10/27/2025 11:37:34 AM CDT

Repair Order #15149

Page:1

Brazoria County Fire Marshal**Phone: 979-864-1121**111 E Locust St
ANGLETON, TX 77515Service Writer : mpiper
Tag/State : 1366530/TX**Vehicle : 2019 Ford F150 1/2 Ton - Pickup 3.3 L 204 CID V6 DOHC**Odometer In : 98223
Odometer Out : 98223

VIN : 1FTEW1CB9KKD16740

Fleet #/Driver :

Created : 10/24/2025 1:20:54 PM CDT

VEHICLE CONCERNS / REASON FOR VISIT**Qty: 1****Price: \$145.00**

CHECK ENGINE LIGHT

RADIO WOULDN'T WORK-- AND WIPERS WOULDN'T WORK EITHER

MPI

Code/Tech*DescriptionPrice

tm*

General Diagnostic

\$145.00

Includes test drive. Scanning all computers on vehicle and performing diagnosis for concern.

TECHNICIAN NOTES/DISCOVERY

On insp. found the check engine light on with dtc P0496. On diag. found the purge valve to be stuck open causing full flow of fuel vapors into the engine.

Need to replace the evap purge valve and retest.

No problem found with the radio or the wipers at this time.

Found the front brake pads to be at 3-5mm and the rear pads 3-4mm.
recommend front and rear brakes.**Warranty Details**

Repairs carry a 12 month/12,000 mile parts and labor warranty from the original repair date and mileage, which ever comes first.

****EXCLUDES THE FOLLOWING****

- Parts provided by customer
- Used or salvage parts
- Maintenance
- Alignments

Select parts carry an independent warranty. See individual parts line for further warranty details.

sw*

MULTI POINT INSPECTION/ ALIGNMENT CHECK \$0.00

PURGE VALVE REPLACEMENT**Qty: 1****Price: \$203.79**Code/Tech*DescriptionPrice

tm*

CANISTER PURGE SOLENOID Remove & Replace

\$68.50

Includes: Component test.

Standard Ignition Vapor Canister Purge Valve

\$135.29

FRONT BRAKE PAD REPLACEMENT**Qty: 1****Price: \$196.52**Code/Tech*DescriptionPrice

tm*

BRAKE SHOES &/OR PADS Remove & Replace

\$110.00

Includes: Clean, lube and/or replace Brake Hardware as necessary. Adjust Brakes (where applicable).

Includes: Repack Wheel Bearings (where applicable).

DOES NOT include refinishing.

BrakeBest Select Pro Ceramic Disc Brake Pad Set

\$86.52

**SS MotorTrendz**

109 E Kiber St

Angleton, TX 77515

(979) 308-4588

Fax (979)-269-7347

Email: jerry@ssmotortrendz.com

Website: ssmotortrendz.com

10/27/2025 11:37:34 AM CDT

Repair Order #15149

Page:2

Brazoria County Fire Marshal**Vehicle: 2019 Ford F150 1/2 Ton - Pickup 3.3 L 204****REAR BRAKE PAD REPLACEMENT****Qty: 1****Price: \$218.52**Code/Tech*DescriptionPrice

tm*

BRAKE SHOES &/OR PADS Remove & Replace \$132.00

Includes: Clean, lube and/or replace Brake Hardware as necessary. Adjust Brakes (where applicable).

Includes: Repack Wheel Bearings (where applicable).

DOES NOT include refinishing.

BrakeBest Select Pro Ceramic Disc Brake Pad \$86.52
Set**BG BRAKE SYSTEM FLUSH SERVICE****Qty: 1****Price: \$139.99**Code/Tech*DescriptionPrice

tm*

BG BRAKE FLUSH SERVICE \$110.00

Removes varnish from the brake system and installs new brake fluid that will prevent master cylinder corrosion.

(Recommended once every 2 years)

DOT 4 BRAKE FLUID \$29.99

#84032

<u>Code/Tech*</u>	<u>Description</u>	<u>Condition</u>	<u>Unit Price</u>	<u>Price</u>
	Labor		\$565.50
	Parts		\$338.32
	Shop Supplies		\$34.95
	Sales Tax		Tax Exempt #	\$0.00
			Repair Total	\$938.77
			PAYMENT	\$0.00
			BALANCE DUE	\$938.77

Approvals

Date & Time	Total Amount	Authorized By	Method	Employee
TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ____ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts _____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.				

X
CUSTOMER SIGNATURE

****We Appreciate Your Business****