

City of Danbury, TX. Culvert Request to Engineer's Office



Date of request: _09/5/25	
Home Owner's name: Yuliana Rodriguez	
Address where culverts are to be installed:	
_1807 avenue G danbury tx	
Home owner's home phone number:	
Home owner's cell phone number: 83233182	48
Culverts must be on site when form is turned	in to the city to make request to county.
What type of Culvert: Cement or HDR p	lastic
Number of culverts to be installed: 4	
Diameter of culverts to be installed: 18	
Is the location marked for setting the culverts	: Yes or NO
Additional notes for installation: (north, south	h, east, or west?)
South	
County will complete work according to their	gahadula
*	
*New culverts being installed 15 inch is require	
* Existing culverts in the area then they must	match which is there.
* If culvert is longer than 48 ft. then clean- ou homeowner and be on site when request is ma	
Request sent on:	
Reply from county received on:	
	GREED Brazeria County Engineer
	ate Approved 9-23-25 Date Completed
	O#
	OMMENTS
Rev. A 1.10.24	



City of Danbury, TX. Culvert Request to Engineer's Office



Date of request: _09/5/25	
Home Owner's name: Yuliana Rodriguez	
Address where culverts are to be installed	ed:
_ 1811 avenue G danbury tx	
Home owner's home phone number:	
Home owner's cell phone number: 8323	
Culverts must be on site when form is tu	rned in to the city to make request to county.
What type of Culvert: Cement or HI	DR plastic
Number of culverts to be installed: 4	
Diameter of culverts to be installed: 18	
Is the location marked for setting the cul-	
Additional notes for installation: (north,	south, east, or west?)
South	
County will complete work according to	<mark>their schedule</mark> .
*New culverts being installed 15 inch is r	equired size.
* Existing culverts in the area then they n	nust match which is there.
* If culvert is longer than 48 ft. then clear homeowner and be on site when request i	n- out openings or grates must be supplied by is made.
Request sent on:	
Reply from county received on:	
	REED
	Brazoria County Engineer te Approved 9-23-25 Date Completed
	O#
	MMENTS
Rev. A 1.10.24	
NEV. A 1.10.24	



City of Danbury, TX.




Culvert Request to Engineer's Office

Date of request: 9-8-2025
Home Owner's name: Wesley Theriot
Address where culverts are to be installed:
1702 Avenue F, Donbury TX 77534
Home owner's home phone number: $281-960-1950$
Home owner's cell phone number: $281-960-1950$
Culverts must be on site when form is turned in to the city to make request to county.
What type of Culvert: Cement or HDR plastic
Number of culverts to be installed:
Diameter of culverts to be installed:
Is the location marked for setting the culverts: Yes or NO
Additional notes for installation: (north, south, east, or west?)
The culvest will be on Avenue f in Front of the new born. Stakes ore placed in the ditch
County will complete work according to their schedule.
*New culverts being installed 15 inch is required size.
* Existing culverts in the area then they must match which is there.
* If culvert is longer than 48 ft. then clean- out openings or grates must be supplied by homeowner and be on site when request is made.
Request sent on:
Reply from county received on:
Brazoria County Engineer Ite Approved 9-23-25 Date Completed O# OMMENTS Rev. A 1.10.24

Tricia Simmons

From: Sent:	Andi Ford <andi@cityofoystercreek.com> Tuesday, September 9, 2025 10:07 AM</andi@cityofoystercreek.com>
To: Subject:	ENGINEER INTERLOCALS [EXTERNAL] John's RV Park - 102 Baldwin - Ditch work
Attachments:	Culverts & Ditchwork for 102 Baldwin, Oyster Creek, TX.pdf
Follow Un Flore	Followup
Follow Up Flag: Flag Status:	Follow up Flagged
saying that the ditches need corner property, so I printed	k request for 102 Baldwin, Oyster Creek, TX. The owner, Mr. Eric Sital, is to be dug out and culverts need to be cleaned all along his property. He has a out his lots and highlighted the areas. s email response to help. Please let me know if I can provide any other
need to be dug and cleaned out. Th in water sitting there longer than it	is ago and about a year ago too. The ditches along Baldwin Rd in front of my RV Park Desperately the converts are almost non visible and don't allow the water to flow out of the subdivision resulting should. The ditch along 523 going towards Levi road need to be dug up and converts cleaned out the tree they turn from Baldwin to 523 (this is where it bottlenecks). My main sewer clean out never use own pours as it does now.
So to answer your question, yes it's	pretty much the whole ditch from Baldwin down to 523 and towards Levi road.
It would be really awesome to get so	ome help with this, and definitely ease some stress that comes with heavy rains.
Thank You	
Andí Ford	
City Secretary	
City of Oyster Creek	
(979)233-0243	
	210
This message has been prepared of	or disseminated using resources owned by Brazoria County and is subject to the
County's policies on the use of Co	unty provided technology. E-CREED
This message has been prepared of County's policies on the use of Co system by any County employee of laws of the State of Texas.	unty provided technology. E-GREED Brazoria County Engineer
County's policies on the use of Co system by any County employee of	unty provided technology. E-GREED Brazoria County Engineer vate Approved 9-23-25 Date Completed
County's policies on the use of Co system by any County employee of	unty provided technology. E-GREED Brazoria County Engineer
County's policies on the use of Co system by any County employee of	unty provided technology. E-GREED Brazoria County Engineer ate Approved 9-23-25 Date Completed VO#
County's policies on the use of Co system by any County employee of	unty provided technology. E-GREED Brazoria County Engineer ate Approved 9-23-25 Date Completed VO#

IB25-OC (OYSTER CREEK) City ID Code 277



102 Baldwin, Oyster Creek Ditchwork + Culverts cleaned out