

Vehicle Inspection Form

Inventory ID: N/A	Asset Number: 1121	Fair Market Value: \$8,385 KBB
Short Description: Year <u>2015</u> Make <u>CHEVROLET</u> Model <u>TRAVERSE</u>		
VIN: <u>1GNKRGKD3FJ220329</u> Title: <input checked="" type="checkbox"/> Clean Title <input type="checkbox"/> Salvage Title <input type="checkbox"/> No Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> Other Odometer: <u>N/A</u> <input type="checkbox"/> Miles <input type="checkbox"/> Kilometers <input type="checkbox"/> Hours Odometer Accurate? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown		
Long Description: This Vehicle: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input checked="" type="checkbox"/> Runs/Drivable <input type="checkbox"/> Engine Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only Engine- Type: <u>3.6 L, V6</u> <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine <input type="checkbox"/> Propane/Natural Gas <input type="checkbox"/> Gas/Electric Hybrid Engine Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> is in unknown condition Repairs needed: <u>Odometer non-functioning</u> This vehicle was maintained every <u>5000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles/Kilometers Date Removed from Service: <u>01/01/2025</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual ___ Speed Condition: <input type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is Unknown Condition Repairs Needed: _____ Drivetrain: <input checked="" type="checkbox"/> 2 Wheel Drive <input type="checkbox"/> 4 Wheel Drive Condition: _____ Exterior: Color: <u>Silver</u> Windows: <input type="checkbox"/> No Cracked Glass <input checked="" type="checkbox"/> Cracked <u>Windshield</u> Minor: <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: <u>Fair</u> Tread: <u>Med</u> #Flat _____ Hubcaps # <u>4</u> Major Damage to: _____ Additional Damage: _____ Decals: <input checked="" type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed or <input type="checkbox"/> Have been Removed & <input type="checkbox"/> Impressions Remain <input type="checkbox"/> No impressions Emergency equip: <input checked="" type="checkbox"/> None <input type="checkbox"/> Has been removed & <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes Interior: Color <u>Tan</u> <input checked="" type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: <u>None visible</u> Damage to Dash/Floor: <u>None visible</u> Radio: <input checked="" type="checkbox"/> Stock or <input type="checkbox"/> Brand & Model: _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input checked="" type="checkbox"/> AM/FM CD AC Condition: <input checked="" type="checkbox"/> Cold <input type="checkbox"/> Unknown <input type="checkbox"/> No AC Air Bags: <input type="checkbox"/> Driver's Side <input checked="" type="checkbox"/> Dual <input checked="" type="checkbox"/> Cruise Control <input checked="" type="checkbox"/> Tilt Steering <input checked="" type="checkbox"/> Remote Mirrors <input checked="" type="checkbox"/> Climate Control Power: <input checked="" type="checkbox"/> Steering <input checked="" type="checkbox"/> Windows <input checked="" type="checkbox"/> Door Locks <input checked="" type="checkbox"/> Seats		
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ <input type="checkbox"/> Tool Box <input type="checkbox"/> Light Bar <input type="checkbox"/> Ladder Rack <input type="checkbox"/> Utility Body: Brand _____ <input type="checkbox"/> Hitch: Type _____		
Location of Asset: <u>BCNTF Building</u> 3602 CR 45, Angleton TX 77515		